## Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: Slawson Exploration Company, Inc.
Well Name/Number: Cleaver 1-30H
Location: SW SW Section 30 T21N R60E
County: Richland, MT; Field (or Wildcat) Wildcat
· ————————————————————————————————————
Air Quality
(possible concerns)
Long drilling time: No, 25-35 days drilling time.
Unusually deep drilling (high horsepower rig): <u>Triple derrick rig to drill a single lateral Horizontal</u>
Bakken well test, 14,564'MD/10,365'TVD.
Possible H2S gas production: Slight chance H2S gas production.
In/near Class I air quality area: No Class I air quality area in the area of review.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under 75-2-
<u>211.</u>
Mitigation:
<u>X</u> Air quality permit (AQB review)
X Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: Gas gathering facilities are available to hookup wellhead gas in this area. Single
lateral, 14,564'MD/10,365'TVD Bakken Formation horizontal well.
Water Quality
(possible concerns)
Salt/oil based mild: Ves intermediate string casing hole will be drilled with oil based invert drilling thirds
Salt/oil based mud: Yes intermediate string casing hole will be drilled with oil based invert drilling fluids.
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.  Porous/permeable soils: No, silty sand clay soils.
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.  Porous/permeable soils: No, silty sand clay soils.  Class I stream drainage: No, Class I stream drainages in the area of review.
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.  Porous/permeable soils: No, silty sand clay soils.  Class I stream drainage: No, Class I stream drainages in the area of review.  Mitigation:
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.  Porous/permeable soils: No, silty sand clay soils.  Class I stream drainage: No, Class I stream drainages in the area of review.  Mitigation:  Lined reserve pit
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.  Porous/permeable soils: No, silty sand clay soils.  Class I stream drainage: No, Class I stream drainages in the area of review.  Mitigation:  Lined reserve pit  X_ Adequate surface casing
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.  Porous/permeable soils: No, silty sand clay soils.  Class I stream drainage: No, Class I stream drainages in the area of review.  Mitigation:  Lined reserve pit  X_ Adequate surface casing Berms/dykes, re-routed drainage
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.  Porous/permeable soils: No, silty sand clay soils.  Class I stream drainage: No, Class I stream drainages in the area of review.  Mitigation:  Lined reserve pit  X_ Adequate surface casing  Berms/dykes, re-routed drainage  X_ Closed mud system
Oil based invert drilling fluids for horizontal leg. Surface casing hole to be drilled with freshwater and freshwater mud.  High water table: No high water table expected in the area of review.  Surface drainage leads to live water: No, closest drainage is O'Brien Creek, about ¼ of a mile to the northeast from this location. Within O'Brien Creek is a stock pond, about 1/4 of a mile to the east from this location.  Water well contamination: No, closest nearby wells are about ½ of a mile to the east from this location.  Depth of these wells are 86' and 1673' in depth. Surface hole will be drilled with freshwater and surface casing will be cemented to surface from 1673'.  Porous/permeable soils: No, silty sand clay soils.  Class I stream drainage: No, Class I stream drainages in the area of review.  Mitigation:  Lined reserve pit  X_ Adequate surface casing Berms/dykes, re-routed drainage

Soils/Vegetation/Land Use

aquifer. Adequate surface casing and operational BOP equipment should prevent any problems.

Comments: 1673' surface casing to be set to protect freshwater zones and to cover the Fox Hills

(possible concerns) Steam crossings: None anticipated. High erosion potential: Yes, location will require moderate cut, up to 28.3' and moderate fill, up to 15.4', Loss of soil productivity: None, location to be restored after drilling well, if nonproductive. If productive unused portion of drillsite will be reclaimed.\_ Unusually large wellsite: No, very large well site 450'X400' Damage to improvements: Slight, surface use is grazing land. Conflict with existing land use/values: Slight Mitigation \_\_ Avoid improvements (topographic tolerance) Exception location requested X Stockpile topsoil \_\_ Stream Crossing Permit (other agency review) X Reclaim unused part of wellsite if productive \_\_ Special construction methods to enhance reclamation Other Comments: Access will be over existing county road, #116. An access road will be built into location off the existing county road, about 1254' new road will be built into this location. Drilling rig will utilize a closed loop mud system. Cuttings will be buried in the lined cuttings pit or trucked to an authorized solids disposal facility. Surface freshwater drilling fluids will be trucked to the next location. Oil based invert drilling fluids will be recycled. Completion fluids will be hauled to a Class II disposal. No concerns. Health Hazards/Noise (possible concerns) Proximity to public facilities/residences: \_Closest residences are about ½ of a mile to the east and about 1.325 miles to the northwest from this location. Possibility of H2S: \_Slight chance H2S.\_

Size of rig/length of drilling time: Triple drilling rig 25 to 35 days drilling time.

Mitigation:

X Proper BOP equipment \_\_ Topographic sound barriers

\_\_ H2S contingency and/or evacuation plan

\_\_ Special equipment/procedures requirements

\_\_ Other:\_

Comments: \_\_Adequate surface casing cemented to surface with working BOP stack should mitigate any problems. Distance is sufficient to mitigate any noise problems.

## Wildlife/recreation

(possible concerns)

Proximity to sensitive wildlife areas (DFWP identified): Little Missouri National Grasslands about 1.5 miles to the east of this location in North Dakota.\_

Proximity to recreation sites: Little Missouri National Grasslands about 1.5 miles to the east of this location in North Dakota.

Creation of new access to wildlife habitat: No

Conflict with game range/refuge management: No

Threatened or endangered Species Threatened or endangered species listed in Richland county by USFW service are Pallid Sturgeon, Piping Plover, Interior Lease Tern and Whooping Crane. Candidate species are the Greater Sage Grouse and the Sprague's Pipit. NH tracker website lists the following as "Species of Concern": six (6) are listed as follows: Meadow Jumping Mouse, Baird's Sparrow, Grasshopper Sparrow, Whooping Crane, Loggerheaded Shrike and Greater Shorthorn Lizard.

Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other:
Comments: Surface grasslands are private. There maybe species of concern that maybe impacted
by this wellsite. We ask the operator to consult with the surface owner as to what he would like done, if a species of concern are discovered at this location.
species of concern are discovered at this focation.
Historical/Cultural/Paleontological
(possible concerns)
Proximity to known sites None identified
Mitigation
<ul><li>avoidance (topographic tolerance, location exception)</li><li>other agency review (SHPO, DSL, federal agencies)</li></ul>
Other:
Comments: Surface grasslands are private. There maybe possible
historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the operator to
consult with the surface owner as to his desires to preserve these sites or not, if they are found during
construction of the wellsite.
Social/Economic
(possible concerns)
Substantial effect on tax base
Create demand for new governmental services
Population increase or relocation Comments: No concerns
Comments. No concerns
Remarks or Special Concerns for this site
A single leteral Human Dakkan Shale harigantal well 14 564'MD/10 265'TVD
A single lateral Upper Bakken Shale horizontal well,14,564'MD/10,365'TVD.
<del></del>
Summary: Evaluation of Impacts and Cumulative effects
No long term impacts expected. Some short term impacts will occur.
I conclude that the approval of the subject Notice of Intent to Drill (does/ <u>does not</u> ) constitute a major
action of state government significantly affecting the quality of the human environment, and (does/ <u>does</u>
<u>not</u> ) require the preparation of an environmental impact statement.
Prepared by (BOGC): /s/Steven Sasaki
(title:) Chief Field Inspector
Date: January 29, 2012
Other Persons Contacted:
(Name and Agency)
_Montana Bureau of Mines and Geology, Groundwater Information Center

website.
(subject discussed)
Water wells in Richland County
(date)
<u>January 29, 2012</u>
US Fish and Wildlife, Region 6 website (Name and Agency) ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA COUNTIES, Richland County (subject discussed)
<u>January 29, 2012</u> (date)
Montana Natural Heritage Program Website (FWP)
(Name and Agency)
Heritage State Rank= S1, S2, S3, T21N R60E
(subject discussed)
<u>January 29, 2012</u> (date)
If location was inspected before permit approval:
Inspection date:
Inspector:
Others present during inspection: